



AGGREGATE, INC.

411 Tiernan Rd. • P.O. Box 1067 • Bay City, MI • 48706 • (989) 667-5990 • Fax (989) 667-5991

Date 3/17/2010 Vessel _____

Material 21AA

State Pit Number 71-3

Quarry Calcite

Sample from stockpile at Bay Aggregate Dock

Pile Location Loading Face

Sieve Size	Retained Weight	Retained Percent	Cumulative % Retained	Cumulative % Passing	Specification Requirements
2 1/2 "					
2 "					
1 1/2 "	0	0.0%	0.0%	100%	100%
1 1/4 "					
1 "	0	0.0%	0.0%	100%	85- 100%
3/4 "	639	16.6%	16.6%	83%	
1/2 "	883	22.9%	39.5%	61%	50-75%
3/8 "	119	3.1%	42.6%	57%	
no. 4	536	13.9%	56.5%	44%	
no. 8	659	17.1%	73.6%	26%	20-35%
no. 16	495	12.8%	86.4%	14%	
no. 30	193	5.0%	91.4%	9%	
no. 50	63	1.6%	93.1%	7%	
no. 100	28	0.7%	93.8%	6%	
no. 200	15	0.4%	94.2%	6%	
pan	3	0.1%	94.3%	6%	
LBW	221	5.7%			
TOTAL:	3853.60	94.27%			

0.00

LOSS BY WASH

5.73%

LBW MAX

10%

Initial Weight 3853.6 g

Weight after Washing 3632.6 g

Loss by Washing 221 g

Accepted X

Rejected _____

MOISTURE

2.90%

Initial Weight 3968.7 g

Dry Weight 3853.6 g

Moisture 115.1 g

Tested By _____

L. Philippi
 Michigan Certified Aggregate Technician
 Cert # 101992-0213