

Bay AGGREGATE, INC.

411 Tiernan Rd. • P.O. Box 1067 • Bay City, MI • 48706 • (989) 667-5990 • Fax (989) 667-5991

Date 3/23/2010 Vessel _____
 Material 31A
 State Pit Number 49-065
 Quarry Cedarville
 Sample from stockpile at Bay Aggregate
 Pile Location Loading Face

Sieve Size	Retained Weight	Retained Percent	Cumulative % Retained	Cumulative % Passing	Specification Requirements
2 1/2 "					
2 "					
1 1/2 "	0	0.0%	0.0%	100%	
1 1/4 "					
1 "	0	0.0%	0.0%	100%	
3/4 "	0	0.0%	0.0%	100%	
1/2 "	0	0.0%	0.0%	100%	100%
3/8 "	7	0.3%	0.3%	100%	95 - 100%
no. 4	1264	58.2%	58.6%	41%	35-65%
no. 8	740	34.1%	92.7%	7%	0-25%
no. 16	94	4.3%	97.0%	3%	
no. 30	16	0.7%	97.7%	2%	
no. 50	0	0.0%	97.7%	2%	
no. 100	0	0.0%	97.7%	2%	
no. 200	0	0.0%	97.7%	2%	
pan	10	0.4%	98.1%	2%	0%
LBW	41	1.9%			
TOTAL:	2170.50	98.13%			

1.10

LOSS BY WASH 1.86% **LBW MAX**

Initial Weight 2171.6 g

Weight after Washing 2131.1 g Accepted _____

Loss by Washing 40.5 g Rejected _____

MOISTURE 0.85%

Initial Weight 2190.3 g Rodded _____

Dry Weight 2171.6 g Shoveled _____

Moisture 18.7 g

Tested By _____

L. Philippi
 Michigan Certified Aggregate Technician
 Cert # 101992-0213